

CREW: 89 WORK ORDER TYPE: REBUILDS

02-60456-15

ISSUE DATE 01/06/11

Page 1 Of 2

Originator : RUSSELL STUBBS
Planner : JIMMIE KNAPP
Drawing No : 1SGA-M2063A
Equip No/Cat: 1SGA--3 2
Project ID :
Shutdown : N No Shutdown
Ref No :
Schedule Date :
Priority : 3A
Clearance : NO
Tag Request :
Text ID : REBUILD*2627
Frequency : NOT SCHEDULED
Last Reading : No Reading

Date Completed: _____
Completed By : _____
Accepted By : _____
Failure Code: _____
Signature : _____
Signature : _____

				** Delay Codes Legend **			
				W=Whse	C=CrSp	T=Tag	TL=Tool
				** Record Time Daily **			
				P=Plan			
				Delays			
Step	Job Scope	MN	DY	Safety and Additional Information	Emp No	Date	Hours
1	RETURN PRINTED OUTPUT BOARD TO FOXBORO FOR REPAIR/REPLACEMENT.	1	1				
	INSURE THERE IS A SHORT DESCRIPTION OF THE PROBLEM FOUND.						
	ADDITIONAL INSTRUCTIONS BY SUPERVISOR.						
	STK NO: 2627						
	QTY: 2						
	ORIG WO: 02-60456-0						
	STK ISSUE: 241616						
	ITEM DESCRIPTION:						
	BOARD, FOXBORO (CCS) ANALOG CONVERTER, DUAL DC						
	MILLI-AMP TO DIGITAL OUTPUT, 4 TO 20 MADC						
	EACH						
	CHANNEL, ISOLATED OUTPUT.						
	FOXBORO P/N 3A2-D21B						

** IMPORTANT NOTICE **

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



02-60456-15A

IP7_037365

CREW: 89

WORK ORDER TYPE: REBUILDS

02-60456-15

ISSUE DATE 01/06/11

Page 2 Of 2

** Work Order Parts List **

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
-----	-----	-----	-----	---	-----	-----	-----
1 DIRECT	REPAIR/REPLACE AND RETURN: BOARD, PRINTED OUTPUT FOXBORO P/N			EA			

IP7_037366